

HarvestLab™ Software Update V147 Release Notes

Important Notes:

This software is updating your HarvestLab™ 3000 sensor to version V147.

To perform the software update, please download the software bundle from StellarSupport™ at HarvestLab™ section. To connect the HarvestLab™ 3000 sensor with your laptop, you must use an Ethernet cable (PFP16262: Ethernet Cable (M12 to RJ45)). Please follow the steps on HarvestLab™ web UI to update the software. (<https://www.youtube.com/watch?v=atQQGueHYJY&feature=youtu.be>)

Release Notes:

Date	Software	Version
March 2024	John Deere Harvestlab™ 3000 sensor	V147

V147

New Feature – Support storing serial spectra for diagnostic.

Enhancement – Showing hours since last reference in web UI

Bug – Fixes

Note: A refresh of the browser is needed after installation of software update.